

UTAH DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS AND MINING 1594 West North Temple - Suite 1210, Salt Lake City UT 84116 (Delivery service)

Box 145801, Salt Lake City UT 84114-5801 (US Postal service)
Telephone: (801) 538-5342

LARGE MINING OPERATIONS PROGRESS REPORT January 1, 2015 to December 31, 2015


The information required in this form is based on provisions of the Mined Land Reclamation Act, Title 40-8, and the R647 rules under the Utah Minerals Regulatory Program. It is due January 31 of each year. Attach additional pages as needed.

| | FED VI 2010 |
|--------|---|
| 1. | Mine Permit Number: S/490 /036 DIV. OF OIL, GAS & MINING |
| 2. | Mine Name: Manning Canyon |
| 3. | Name of Operator/Permittee: Pabco Clay Products LLC, dba Interstate Brick Company Note: If Operator's address, company representative and/or phone number have changed, submit replacement page(s) for the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/MINES/Minerals_Related/FORMS/MR-REV.pdf . |
| 4. | Report the gross amount of ore or product mined and waste moved. |
| | Gross ore or product mined 7,812 (amount) tons (unit) |
| | Waste material moved (amount) (unit) |
| | Disposition of ore and waste: <u>clay stockpiled to be hauled offsite. Overburden salvaged for topsoil.</u> Primary Commodities Produced |
| 5. | Total disturbed area from previous reporting year New disturbance created during current reporting year Total disturbed area at the end of this reporting year Total disturbed area at the end of this reporting year Marea was gpsed with DOGM 2/15 for bond adjustment. |
| | total disturbed area includes reporting year and previous year disturbances minus areas of regrading and reseeding ave received approval for bond release. The Total area should not be greater than the permitted/bonded acreage. |
| 6. | Areas of reclamation eligible for bond release: Areas regraded during the year Areas reseeded during the year Areas reseeded during the year ** To apply for full or partial bond/site release submit form MR-SITE available at the Divisions web page at https://fs.ogm.utah.gov/pub/MINES/Minerals_Related/FORMS/MR-SITE.pdf . See application for Bond Release, 1/25/16, for S/490/036) |
| 7. | Briefly describe reclamation work performed during current reporting year. If there was no production shown in Line 4, describe any maintenance work conducted that required earthmoving equipment. Include an updated map depicting surface disturbance and reclamation performed during the year (per R647-4-121.2) and any updates to the operation plan (per R647-4-106). In 2015 most of the mining area was re-graded after mining (legend item: area reclaimed 2015-7 acres) and overburden redistributed even the area. The same was done in 2014. |
| I here | .7 acres) and overburden redistributed over the area. The same was done in 2014. by certify the information provided in this report is true and correct to the best of my knowledge and belief. (Typed or Print): John Hewitt |
| Title | of Operator: Assistant Plant Manager |
| Signa | ture of Operator: |
| Date: | 1/28/16 |

O:\FORMS\reports\Annual reports-2015\MR-AR-LMO2015 MB.doc

2015 MR-AR Annual Report Map Manning Canyon Mine, S/490/036 Pabco Clay Products, LLC dba Interstate Brick Co.





Legend

Area reclaimed 2015- .7 acres

Overburden pile redistributed over 2014 reclaim area, 3,531 CY

2014 reclaimed area contoured, .7 acres (see pile redistributed)

Ephemeral Streambed (not disturbed)

ephemeral stream bed Drain Pipe

Road from Hwy. with new turn around

Estimated Disturbed since life of mine, 2013 - 2.7 acres

Clay bank

Mercur 7.5 Min & Rush Valley 100K Maps Township 6 South, Range 3 West, SLB&M Sections 21 & 22